

**Page Denied**

**SECRET**

25X1

**(c) NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER**Page 1 of 1

Attachment to Z-11825/82

Copy 64

NPIC/PEG (12/25)

**POSTLAUNCH ACTIVITY  
TYURATAM ICBM LAUNCH TEST SITE S10, USSR**

25X1

1. (SWN) SIGNIFICANCE: POSTLAUNCH ACTIVITY FROM A RECENTLY LAUNCHED SS-19 CONTINUES AT TYURATAM.
2. (SWN) REMARKS: A SPENT SS-19 MISSILE CANISTER HAS BEEN REMOVED FROM THE SILO AT S10 AFTER A RECENT LAUNCH ATTEMPT FAILED. THE SPENT CANISTER IS ON A SILO LOADER AND IS BACKED UP TO A CANVAS-COVERED MISSILE TRANSPORTER. THE SPENT CANISTER DOES NOT APPEAR TO BE EXTERNALLY DAMAGED BEYOND THE NORMAL SCORCHING THAT RESULTS FROM A LAUNCH. A LARGE TRUCK-MOUNTED CRANE, NORMALLY NOT SEEN AT A SILO, HAS THE BOOM EXTENDED OVER THE OPEN SILO AND MAY BE REMOVING DAMAGED PARTS. THREE POSSIBLE DAMAGED PARTS AND THE EXHAUST DEFLECTOR RING ARE NEAR THE OPEN SILO.

(SWN) [REDACTED] A BLAST MARK WAS AROUND THE OPEN SILO, AND A MAZ-543 UPPER CANISTER TRANSPORTER AND A TRUCK-MOUNTED CRANE WERE PARKED AT THE SILO. AN IMPACT CRATER AND BURN AREA WAS NEAR TEST SITE G1 A/B.

25X1

3. [REDACTED] COORDINATES 46-04-14N 062-57-25E

25X1

COMMENTS AND QUERIES REGARDING THIS BRIEFING BOARD MAY BE DIRECTED [REDACTED]

25X1

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing board(s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue.

25X1

**WARNING NOTICE**  
Intelligence Sources  
and Methods Involved

**SECRET**

25X1